



Image supplied courtesy of Fortescue Metals Group Ltd

## Smart technology minimises production disruption

Conti™MultiProtect continually monitors 14 stockyard belts at this Anderson Point iron ore stockyard in the Pilbara. One successfully detected an early belt rip, automatically shutting down a vital conveyor for repair before any further significant and very costly damage was caused.

- > Prevent costly damage > Prevent downtime incidents > Increase belt lifetime
- > Increase up-time, system availability and reliability > Flexible operation according to your requirements. Contact us now and get better conveyor belt performance for your site.



Monitoring is visible on demand by multiple users at the same time from any nominated desktop, laptop or through alerts issued to site operational systems, email or SMS

ContiTech Australia Pty Ltd  
www.contitech.net.au  
+61 3 9721 0600 Melbourne VIC  
+61 8 6240 3500 Perth WA

+61 8 9186 0500 Karratha WA  
+61 7 4841 9800 Mackay QLD  
+61 2 8839 9600 Parramatta NSW  
+61 2 4966 3493 Beresfield NSW

**ContiTech**